

VIZ-ART LEADER Mount

Universal projector mount:

- Direct
- Adjusted 48 – 74
- Adjusted 66 – 110
- Adjusted 120 - 200




LIST OF ITEMS:

- Projector mount:
- Universal projector adapter
- Adjusted arm (mount with arm)
- Mounting set
- Installation manual
- Mounting template

1. Installation:


- A. Prepare an installation place and mark mounting points using installation template as below:




Install mount to the ceiling

- B. Install projector on universal projector adapter. Use mounting screws from mounting set.

Warning! To connect the mount with the projector, select the appropriate screws from the mounting kit according to the recommendations of the projector manufacturer.




- C. Joint adapter with installed projector with projector mount as described below using middle hanger. Block projector on a mount with screws in holes A.



- D. Check and adjust proper projected image. If needed adjust projector image on a ceiling mount.


2. Adjusting projector on a ceiling mount:

A. Adjusting height of installed projector: Loosen screw B and adjust expected height of projector. Tighten screw- B. In Direct Mount height is non adjustable




B. Image adjustment.


If projected image is too low or high on the screen/vertical distortion/Loosen screws C and tilt projector to expected vertical position. Tighten screws C, when finished.



C. Projector adjustment.
If projected image is too right or left on the screen/horizontal distortion/,- rotate projector on a screw D.



D. Horizontal / parallel image from the projector adjustment.
Loosen screws E. then adjust the projector mount's roll adjustment such that the top and bottom edges of the image are approximately horizontal and aligned with the top and bottom of the screen. Tighten screws E, when finished.



3. Technical Specification:

Product model:

VIZ-ART LEADER Mount

Adjustment:

Up-down 15 degrees
Right-left 15 degrees
Horizontal 18 degrees
Tilt 56 degrees (with heights)

Weight:

LEADER Mount direct 1,1 kg
LEADER Mount 48 -74 with heights 3 kg
LEADER Mount 66-110 with heights 4 kg
LEADER Mount 120-200 with heights 6,5 kg

4. Mounting kit set :

Bolts:

M4x12 – 4 pcs.;
M5x12 – 8 pcs.;
M6x12 – 4 pcs.;

Washers:

ø6x12 – 8 pcs.;
ø5x10 – 4 pcs.;

Wall plugs:

ø8x40 – 4 pcs.;

Screws:

ø5x40 flat head – 4 pcs.;

manufactured: VIZ-ART Automation
tel.+48 22/6138899 www.viz-art.eu